


# Lessons Learned From a 24-inch FM Inspection


Chandler Carpenter

# Phoenix's Force Mains

- 70 miles of 4-inch to 48-inch
- 28 lift stations
- Earliest construction: 1972



# Lift Station 43 Force Main Overview




## Project Background

- Three parallel 24-inch DIP barrels
- 1.5 miles from LS 43 to DV-1&2
- 2001 – Original FM Construction
- Prior failures

## Project Goals

- Perform condition assessment
- Repair recommendations
- Remaining useful life extension

# LS43 FM Assessment Overview



# Inspection Technology & Platform Selection



## Technology

- Remote field electromagnetics

## Platform

- PICA See Snake Tool


## Information obtained

- Locations of pipe wall thinning
- Resolution - 10% wall loss / 1-sq.in

## Inspection requirements



- Full diameter pipe access
- Debris removed from pipe
- Constant flowrate

# Assessment Plan: Barrel 1 Example





# Extensive Preparation: *Tool Launching Set-up*




**Tool Requirement:**  
Full diameter  
access to pipe



**Inspection Prep:**  
Install temporary  
launch piping

# Extensive Preparation: *Tool Conveyance Set-up*



**Risk:** Tool stopping



**Mitigation:** Provide constant flow rate.

**Risk:** Spills

**Mitigation:** Vac-truck on site, containment, post-inspection clean-up.




**Risk:** Cross-contamination

**Mitigation:** Using backflow preventor, air gap, and frac-tank







# Extensive Preparation: Temporary Valve Replacement



**Tool Requirement:** Full diameter access to pipe

**Inspection Prep:** Replace reduced port plug valves with spool pieces

# Extensive Preparation: Tool Retrieval



**Risk:** Working in/near traffic

**Mitigation:** Traffic control plan

**Risk:** Confined space in vaults

**Mitigation:** Remove vault lid



**Risk:** Equipment entering SRO/SAI

**Mitigation:** Tool-catching basket

# Extensive Preparation: *Progressive Pigging*

**Risk:** Tool stopping

**Mitigation:** Clear the line of grit, grease, and other debris by pigging.





# Extensive Preparation Summary

TYPE	RISK	MITIGATION
Safety	Confined space in vaults	Remove vault lid
	Working in/near traffic	Traffic control plan
	Hazardous H2S exposure	Hazmat suit near discharge vault
Operations	Service disruption	One barrel always in service
	Tool stopping	Modifications, pigging, constant flow rate, and tool tracking
	Equipment entering SRO/SRI	Tool-catching basket
	Over pressurizing main	Pressure test prior to project begins
Public	Spills	Vac-truck on site, containment, post inspection clean-up
	Cross contamination	Using backflow preventor and frac-tank
	Traffic disruption	Higher traffic control during tool retrieval only



# Ready for Barrel 1 Inspection


- ✓ Safety mitigation complete
- ✓ Operational mitigation complete
- ✓ Public impacts mitigation complete
- ✓ Pipeline prepared
- ✓ Tool tracking prepared

August 28, 2020  
4:00 AM Tool is launched



# Barrel 1 Unexpected Challenge

12:30 PM Tool stopped moving here




# Barrel 1 Inspection Recovery



Step 1:  
Team  
meeting



Step 2:  
Excavate &  
locate tool




14 of 26



# Barrel 1 Inspection Recovery

## Step 3: Investigate Root-cause



- 1.2" ID reduction at 45-deg bend
- Abrupt transition

## Step 4: Implement Mitigation



- Grout applied at lip
- Gradual and smooth ID transition

## Step 5: Tool Retrieval



- Increased flow and flushed tool out

*Calm collaboration and experience lead to recovery*



# Next Steps


Assumed diameter reduction present in Barrels 2 and 3



Tool modifications completed to mitigate diameter reduction



Continued with Barrel 3 inspection only (Barrel in service 20+ years)




# Barrel 3 Inspection Completed

## Inspection Prep Completed


- ✓ Safety mitigation complete
- ✓ Operational mitigation complete
- ✓ Public impacts mitigation complete
- ✓ Pipeline prepared
- ✓ Tool tracking prepared

## Tool Launched


## Tool Extracted



## Barrels 1 & 3 Inspection Results



# Inspection Results: Number of Defects



## Findings





Correlation between pipe in service & # of defects



No correlation between negative pressures and air pockets & # of defects



# Inspection Results: Defect Location



## Findings




**Damage concentrated below springline**



**No correlation between negative pressures and air pockets & defect location**

# Damage Mode: Low Velocities

# of Pumps in Operation	One Barrel, fps	Two Barrels, fps	Three Barrels, fps
1	3	1.8	1.3
2	4	3.0	2.2
3	4.4	3.6	2.9



## Findings

### Low Velocities

Results in solids accumulation and internal corrosion

## Recommendations

### Required Velocities to Prevent Accumulation:

Normally operate at 4-5 fps





Increase to  $\geq 6$  fps once per day

# CCTV Inspection Observations

Scenario 1

Scenario 2

Scenario 3



## Inspection Type

- █ RFEM Inspection Only
- █ CCTV Inspection Only
- █ RFEM and CCTV Inspection
- █ No Internal Inspection

## EM Inspection Results

- % Remaining Wall**
- ~ 80%+
  - ~ 60% to 80%
  - ~ 40% to 60%
  - ~ 20% to 40%
  - ~ 0% to 20%
  - ~ No RFEM Inspection

## Internal Visual Observations (CCTV)

- ▲ Corrosion Staining
- ⊕ Lining Defect

# LS 43 and South Valve Vault-1


Scenario 1

Scenario 2

Scenario 3




Install new 2-inch ARV at STA 27+00 on each Barrel





# Lessons Learned

Inspections don't always go as planned.



Experience & calm collaboration increases the likelihood of a successful recovery.



THANK YOU

# Discussion